



# Change in Recommendation for Stellantis Vehicles

In 2024, Stellantis introduced the 5W-30 engine oil specification, FPW9.55535/03, following a recall. This new oil is now mandatory for a wide range of Stellantis engines. Previously, MPM 05000PC 0W-30 or 05000PC-FE 0W-20 was recommended for these engines, but due to the recall, the recommendation has changed to MPM 05000ST 5W-30 with the FPW9.55535/03 specification.

Stellantis has recently expanded this requirement: the 5W-30 oil with specification FPW9.55535/03 is now mandatory for all 1.2-litre PureTech EB2xxx engines (excluding EB2LTxx) and for 2.2-litre DW10Fx engines. Please note that oil service tags or service books may still show outdated recommendations. To ensure you are using the correct product for your vehicle, always consult the MPM website, which is continuously updated with the latest specifications.

## 05000ST Motor Oil 5W-30 Premium Synthetic ST

### Specifications:

- ★ ACEA C3
- ★ API SN Plus
- ★ PSA B71 2290 / B71 2297
- ★ Stellantis FPW9.55535/03

### Find the right product

Want to make sure you are using the right product? Always check [www.mpmoil.com](http://www.mpmoil.com) for the prescribed product and the fluid change interval.

### Packaging units:

ART. NR.	VOLUME	PER UNIT	PER PALLET
05001ST	1 L	6	450
05005ST	5 L	4	112
05020ST	20 L	1	30
05060ST	60 L	1	6
05205ST	205 L	1	2

### In case of technical inquiries

Contact MPM Technical Support at [support@mpmoil.com](mailto:support@mpmoil.com) or call +31 (0)15 - 251 40 30.



**MPM International Oil Company B.V.**

Cyclotronweg 1, 2629 HN Delft, The Netherlands

Phone: +31 (0)15 - 251 40 30 • Internet: [www.mpmoil.com](http://www.mpmoil.com) • E-mail: [info@mpmoil.com](mailto:info@mpmoil.com)

